

General Environmental Incident Summary

Incident: 3220 **Date/Time Notice:** 2/28/2014 0530 **DEM Incident No:**
Responsible Party: Dakota Plains Holdings, Inc.
Date Incident: 2/28/2014 **Time Incident:** 0530 **Duration:** 1 minutes
County: Mountrail **Twp:** 152 **Rng:** 92 **Sec:** 20 **Qtr:**
Lat: 47.87830 **Long:** -102.47140 **Method:** Address matching
Location Description: 3889 88th Ave NW NewTown, ND 58763

Submitted By: James Tate **Affiliation:** Vice President of Operations
Address: 3889 88th Avenue NW
City: New Town **State:** ND **Zip:** 58763

Received By:

Contact Person: James Tate
3889 88th Ave NW
New Town, ND 58763

Distance Nearest Occupied Building: 500 Feet

Type of Incident: Fitting Failure

Description of Released Contaminant: Crude Oil

Volume Spilled: 42.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Release was the result of a pipe fitting failure at on a load out structure.

Risk Evaluation:

No Immediate risks to human health.

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 09 - other

Potential Environmental Impacts:

Environmental impacts from the spill should be minimal. The loading area is enclosed, and the majority of the spill was contained within the containment area directly beneath the cars. Impacted ballast materials are being removed. The building that the spill occurred in is not heated. The frozen ground and ballast materials will not allow for easy migration of the product before it will be excavated.

Action Taken or Planned:

Release occurred inside an enclosed facility. One barrel is estimated to have spilled before the leak could be stopped. Approximately 75 percent, roughly 32 gallons, were contained inside the track pans that lead to the oil water separator. Impacts to the railcars will be wiped down with and absorbent material and cleaned further via a soap or solvent. Impacted ballast materials will be removed and properly disposed of.

Wastes Disposal Location: Clean Harbors Landfill in Sawyer, ND

Agencies Involved:

Updates

Date: 3/3/2014 ***Status:*** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Volume:

Notes:

Release, due to valving failure, remained on location according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental and BIA.